

# Electronics List

For SoLID EC Test  
and PRad SFT Prototype

Zhihong Ye

# Three Racks in the Laber Lab

- One of them has a possible usable VME crate





# From Brad in Hall-C

- PC with CODA 2.6 installed



- NIM Crate



- Power Supply





# From Sergey in Hall-B


- FastBus Crate and few ADC cards





# From Jack in Hall-A

- An oscilloscope and a VME crate and cables



# Beta Source



- The Laser Lab will be a Rad. Control Area!

**Wear your Dosimeters!**

- A RadCon Sign and a Rad. Source Box with Lock will be installed tomorrow.
- Only I can access the source now. If you also want to use the source, I need to add your name to the authorized list.



# What else?

- Internet. (Alex is making a request)
- HV cables (I will get some from P. S. B.)
- Multimeter & Other tools.
- Flash ADC + associates.
- What SoLID need to test
- CAMAC? or what else do we need?
- For my SFT only:

One Power Supply to provide +/- 5V

One Power Supply to provide ~80V

Electric Iron